



**Figure 10. Issues identified during the construction observation process at the Student Center.**

Generally, it should not be necessary to remove a wall to gain access for fire damper inspection and maintenance (left). Most fire and smoke dampers require access for more than just inspection; planning to access the components on the far side of the duct through an 8-in. x 12-in. opening 36-in. away is probably not realistic (right).